

## Subject: Scissor Stack Pin and Bushing Inspection:

This is to remind all owners of the Skid-Lift 1505s / 1805s / 2306s / 1908E HD that annual inspection and maintenance of all pins and bushings located in the scissor stack and plastic slide blocks do require periodic maintenance and inspection. This is recommended by the Aerial Lift Manufacturers Association regardless of brand or model of lift. Failure to inspect pins and bushings on a regular basis can result in damage and possible injury if not maintained. Pins do need to be removed in order to inspect them for possible cracks, bending, or grooving. The greaseless bushings in the scissor stack should also be inspected for possible wear or breakage. The pins and bushings in the scissor stack do not require normal greasing intervals. Please refer to procedures for each specific model on our website under the "Service" tab to find specific instructions for your particular model.

We recommend the following inspection intervals for the usages below:

High usage (Used daily)
Every 6 months

• Low to Medium usage (3-4 times a week) Every 12 months

This service can be done by the user if they have experience working on equipment or by a local equipment mechanic. We'd also like to remind you that snap rings must be discarded and replaced with new ones once they are taken off. Skid-Lift offers snap ring replacement kits with instructions which are available for all lift models. Pin and greaseless bushing replacements can also be purchased upon request if needed.

It also is stated within your Skid-Lift owner's manual that your lift should be inspected by an experienced equipment mechanic every 12 months. This will ensure your safety and longevity of your Skid-lift. All inspection forms and instructions, maintenance procedures, and info can be found on the service tab of our website at: <a href="Service - Skid-Lift">Service - Skid-Lift</a> (skid-lift.com)

We are hoping this reiterates the importance of maintenance for your Skid-Lift. If you have any other questions, please do not hesitate to call.