

Subject: Greaseless Bushings in Skid-Lift Scissor Stack (All Models):

All current models of Skid-Lifts which include the 1505s, 1805s, 2306s, and 1908E HD lifts, the lifts have been outfitted with greaseless bushings. Along with this, all "s" model lifts have increased pin diameter sizes to further reduce the possibility of wear on the pins. This means there are no grease zerks in the scissor stack except for on each side of the hydraulic cylinders.

Here is a couple of photos to show the pin and greaseless bushing set-up:



Along with the greaseless bushings, Skid-Lift has locked the pin from movement on the inner arms further reducing any possibility of wear of the inner arms. This means that pin rotates only on the wear bushings or the plastic slide blocks at the top of the bottom of the lift. This can be seen in the photos below:



Note: It is important that pins and bushings should still be inspected for wear or damage per the normal suggested maintenance schedule.